

Cleanup Site Details

Cleanup Site ID: 14787 Facility/Site ID: 48336 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 14787

Cleanup Site Name: Stewart House Glossary

Alternate Names: Stewart House

LOCATION

Address: 1733 BELMONT AVE City: SEATTLE Zip Code: 98122 County: King

Latitude: 47.61734 Longitude: -122.32490 WRIA: 8 Legislative District: 43 Congressional District: 7 TRS: 25N 4E 32

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Wall, Zak Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Stewart House
 Upland
 Awaiting Cleanup
 NW
 Wall, Zak
 Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

 MEDIA

 Contaminant
 Soil
 Groundwater
 Surface Water
 Sediment
 Air
 Bedrock

 Petroleum-Diesel
 C
 Image: Contaminant of the petroleum of the petroleu

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

End Date/ Status **Start Date** Activity **Completion Date** Site Discovery/Release Report Received Completed 7/18/2017 Initial Investigation / Federal Preliminary Assessment Completed 9/24/2018 Completed 10/31/2018 Early Notice Letter(s) 6/10/2024 Order/Decree/Amendment In Process SHARP Assessment Completed 2/13/2025

Toxics Cleanup Program Report Generated: 10/28/2025 Page 1 of 1