

Cleanup Site Details

Cleanup Site ID: 14795

Cleanup Site ID: 14795 Facility/Site ID: 44830 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)
 Cleanup Site Name: Chelan PUD Worthen Substation [Glossary](#)

Alternate Names: Chelan PUD Worthen Substation

LOCATION

Address: 500 S WORTHEN ST City: WENATCHEE Zip Code: 98801 County: Chelan
 Latitude: 47.41874 Longitude: -120.30352 WRIA: 45 Legislative District: 12 Congressional District: 8 TRS: 22N 20E 10

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
 Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
 Site Rank: N/A NFA Reason: N/A Brownfield? No
 Site Manager: Mefford, John Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chelan PUD Worthen Substation	Upland	Awaiting Cleanup	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	C	C				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/15/2018
Initial Investigation / Federal Preliminary Assessment	Completed		10/25/2018
Early Notice Letter(s)	Completed		10/26/2018
Order/Decree/Amendment	In Process	2/5/2024	
Non-LUST Ind Report Received	Completed		2/6/2024