

Cleanup Site ID: 14795

Cleanup Site Details

Facility/Site ID: 44830 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 14795

Cleanup Site Name: Chelan PUD Worthen Substation

Alternate Names: Chelan PUD Worthen Substation

LOCATION

Address: 500 S WORTHEN ST City: WENATCHEE Zip Code: 98801 County: Chelan

Latitude: 47.41874 Longitude: -120.30352 WRIA: 45 Legislative District: 12 Congressional District: 8 TRS: 22N 20E 10

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Mefford, John Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chelan PUD Worthen Substation	Upland	Awaiting Cleanup	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Ir	strument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
		ivieuia			Number	Country	

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	С	С				
Petroleum-Diesel	С	С				
Petroleum-Gasoline	С	С				
Petroleum-Other	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed		8/15/2018		
Initial Investigation / Federal Preliminary Assessment	Completed		10/25/2018		
Early Notice Letter(s)	Completed		10/26/2018		
Order/Decree/Amendment	In Process	2/5/2024			
Non-LUST Ind Report Received	Completed		2/6/2024		
SHARP Assessment	Completed		9/4/2025		

Toxics Cleanup Program Report Generated: 11/10/2025 Page 1 of 1