Cleanup Site Details

Cleanup Site ID: 14795

Cleanup Site ID: 14795 **Facility/Site ID:** 44830 **UST ID:** N/A Site Page | Site Documents | View Map

Cleanup Site Name: Chelan PUD Worthen Substation Glossary

Alternate Names: Chelan PUD Worthen Substation

LOCATION

Address: 500 S WORTHEN ST **City:** WENATCHEE **Zip Code:** 98801 **County:** Chelan

Latitude: 47.41874 **Longitude:** -120.30352 **WRIA:** 45 **Legislative District:** 12 **Congressional District:** 8 **TRS:** 22N 20E 10

DETAIL

Status: Awaiting Cleanup **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No

Site Manager: Mefford, John **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chelan PUD Worthen Substation	Upland	Awaiting Cleanup	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Benzene	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other	C	C				

Key:
B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated
RA - Remediated-Above
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/15/2018
Initial Investigation / Federal Preliminary Assessment	Completed		10/25/2018
Early Notice Letter(s)	Completed		10/26/2018
Order/Decree/Amendment	In Process	2/5/2024	
Non-LUST Ind Report Received	Completed		2/6/2024