

Cleanup Site Details

Cleanup Site ID: 14850

Cleanup Site ID: 14850 Facility/Site ID: 25893 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: GrayBar Electric [Glossary](#)

Alternate Names: 1414 CENTER ST WASTE SITE, GrayBar Electric, WA EGY 1414 Center Waste Site

LOCATION

Address: 1414 CENTER ST City: TACOMA Zip Code: 98409 County: Pierce
Latitude: 47.23333 Longitude: -122.45231 WRIA: 10 Legislative District: 27 Congressional District: 6 TRS: 20N 3E 8

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Praisewater, Thomas Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
GrayBar Electric	Upland	Awaiting Cleanup	SW	Southwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents		C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/3/2019
Early Notice Letter(s)	Completed		1/23/2019