

Cleanup Site Details

Cleanup Site ID: 15139

Cleanup Site ID: 15139 **Facility/Site ID:** 49919 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Duwamish Waterway Park [Glossary](#)
Alternate Names: 1024 S Elmgrove St, Duwamish Waterway Park, Duwamish Waterway Park Addition, DWP, DWP Addition, United Site Services of Nevada Inc Sea

LOCATION

Address: 7900 10TH AVE S **City:** SEATTLE **Zip Code:** 98108 **County:** King
Latitude: 47.53104 **Longitude:** -122.31986 **WRIA:** 9 **Legislative District:** 11 **Congressional District:** 9 **TRS:** 24N 4E 32

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** Yes
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Johnson, Beau **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|---------------------------------|-----------|-----------------|-----------|---------------|---------------------------------|
| Duwamish Waterway Park | Upland | Cleanup Started | NW | Johnson, Beau | Ecology-supervised or conducted |
| Duwamish Waterway Park Addition | Upland | Cleanup Started | NW | Johnson, Beau | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|----------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Arsenic | C | S | S | | | |
| Lead | C | S | | | | |
| Mercury | C | S | S | | | |
| Metals - Other | C | S | S | | | |
| Other Halogenated Organics | C | S | S | | | |
| Other Non-Halogenated Organics | C | S | S | | | |
| Polychlorinated biPhenyls (PCB) | C | S | S | | | |
| Polycyclic Aromatic Hydrocarbons | C | S | S | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| Site Discovery/Release Report Received | Completed | | 5/30/2019 |
| Non-LUST Ind Report Received | Completed | | 5/30/2019 |

Cleanup Site Details

Cleanup Site ID: 15139

| SITE ACTIVITIES | | | |
|--|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Non-LUST Ind Report Received | Completed | | 5/30/2019 |
| Non-LUST Ind Report Received | Completed | | 5/30/2019 |
| Initial Investigation / Federal Preliminary Assessment | Completed | | 1/28/2020 |
| Early Notice Letter(s) | Completed | | 2/5/2020 |
| VCP Receipt of Plan or Report | Completed | | 7/1/2020 |
| VCP Opinion on Remedial Investigation | Completed | 7/15/2020 | 10/27/2021 |
| VCP Receipt of Plan or Report | Completed | | 8/24/2021 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 6/15/2022 | 10/10/2022 |
| Hazardous Sites Listing/NPL | Completed | | 10/28/2022 |
| Order/Decree/Amendment | In Process | 10/28/2022 | |
| Remedial Investigation and/or FS Work Plan | In Process | 1/12/2024 | |