

Cleanup Site Details

Cleanup Site ID: 15139

Cleanup Site ID: 15139 Facility/Site ID: 49919 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Duwamish Waterway Park [Glossary](#)

Alternate Names: 1024 S Elmgrove St, Duwamish Waterway Park, Duwamish Waterway Park Addition, DWP, DWP Addition, United Site Services of Nevada Inc Sea

LOCATION

Address: 7900 10TH AVE S City: SEATTLE Zip Code: 98108 County: King
Latitude: 47.53104 Longitude: -122.31986 WRIA: 9 Legislative District: 11 Congressional District: 9 TRS: 24N 4E 32

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
Site Manager: Johnson, Beau Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Duwamish Waterway Park	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted
Duwamish Waterway Park Addition	Upland	Cleanup Started	NW	Johnson, Beau	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C	S	S			
Lead	C	S				
Mercury	C	S	S			
Metals - Other	C	S	S			
Other Halogenated Organics	C	S	S			
Other Non-Halogenated Organics	C	S	S			
Polychlorinated biPhenyls (PCB)	C	S	S			
Polycyclic Aromatic Hydrocarbons	C	S	S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		5/30/2019
Non-LUST Ind Report Received	Completed		5/30/2019

Cleanup Site Details

Cleanup Site ID: 15139

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		5/30/2019
Non-LUST Ind Report Received	Completed		5/30/2019
Initial Investigation / Federal Preliminary Assessment	Completed		1/28/2020
Early Notice Letter(s)	Completed		2/5/2020
VCP Receipt of Plan or Report	Completed		7/1/2020
VCP Opinion on Remedial Investigation	Completed	7/15/2020	10/27/2021
VCP Receipt of Plan or Report	Completed		8/24/2021
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/2022	10/10/2022
Hazardous Sites Listing/NPL	Completed		10/28/2022
Order/Decree/Amendment	In Process	10/28/2022	
Remedial Investigation and/or FS Work Plan	In Process	1/12/2024	