	DEPARTMENT OF
	ECOLOGY
1	State of Washington

Cleanup Site Details

Cleanup Site ID: 1544

Cleanup Site ID: 1544 Facility/Site ID) : 7018698	UST ID: N/A		<u>Site</u>	Page Si	<u>te Documer</u>	<u>ts</u>	<u>View Map</u>		
Cleanup Site Name: Deer Trail Mine										
Alternate Names: Deer Trail Mine										
LOCATION										
Address: Fruitland Valley Rd C			City: FRUITLAND Zip C			ode: 99129 County: Stevens				
Latitude: 48.03516 Longitude: -118.09553	WRIA: 58 Legislative Dist			Congressional District: 5 TRS: 29N 37E 1						
DETAIL										
Status: Awaiting Cleanup N	ng Cleanup NFA Received?			No Is PSI site? No						
Statute: MTCA N	FA Date:	N/A	N/A Current VCP? No				Past VCP? No			
Site Rank: N/A N	FA Reason:	N/A Brownfield? No								
Site Manager: Eastern Region	astern Region Responsible Unit: Eastern Active Institutional Control?						No			
CLEANUP UNITS										
Cleanup Unit Name Unit Ty	Unit Type Unit Status		Resp Unit	Unit Mana	ager	Current Process				
Deer Trail Mine Upland	d Awaiting Cleanup		EA	Eastern Region		No Process				
ACTIVE INSTITUTIONAL CONTROLS										
Instrument Type Restriction Redia	Restrictions/Requirements			Date Recording Number		Recording County		Fax Parcel		
There are no current Institutional Controls in effect for this site.										
AFFECTED MEDIA & CONTAMINANTS										
MEDIA										
Contaminant	So	il Ground	water	Surface Wat	er Sedir	ment A	\ir	Bedrock		
Metals Priority Pollutants	C									
Key:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below										
SITE ACTIVITIES										
Activity			Status		Start Date		End Date/ Completion Date			
Site Discovery/Release Report Received	C	Completed 6/1/2004				1/2004				