

Cleanup Site Details

Cleanup Site ID: 165

Cleanup Site ID: 165 Facility/Site ID: 1372 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Woodworth & Co Inc Lakeview Plant

[Glossary](#)

Alternate Names: WOODWORTH & CO INC, Woodworth & Co Inc Lakeview Plant, WOODWORTH & CO LAKEVIEW GRAVEL, WOODWORTH & CO LAKEVIEW GRAVEL PIT, WOODWORTH & COMPANY INC - LAKEVIEW

LOCATION

Address: 2800 104TH STREET CT S **City:** TACOMA **Zip Code:** 98499 **County:** Pierce
Latitude: 47.16327 **Longitude:** -122.47542 **WRIA:** 12 **Legislative District:** 29 **Congressional District:** 10 **TRS:** 19N 3E 6

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** Yes **Past VCP?** Yes
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Hunt, Joe **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Woodworth & Co Inc Lakeview Plant	Upland	Cleanup Started	SW	Hunt, Joe	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C				
Metals Priority Pollutants	C	C				
Petroleum Products-Unspecified	S	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Early Notice Letter(s)	Completed		5/17/1995
Site Hazard Assessment	Completed	3/6/2003	8/11/2003
Hazardous Sites Listing	Completed		8/11/2003
VCP Opinion on Feasibility Study	Completed	8/26/2009	11/10/2009
VCP Receipt of Plan or Report	Completed		1/22/2010
VCP Opinion on Cleanup Action Plan	Completed	1/22/2010	6/17/2010
VCP Opinion on Cleanup Action Plan	Completed	1/22/2010	5/19/2010

Cleanup Site Details

Cleanup Site ID: 165

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Remedial Investigation	Completed	12/6/2010	2/15/2011
VCP Receipt of Plan or Report	Completed		3/30/2011
VCP Receipt of Plan or Report	Completed		6/8/2011
VCP Receipt of Plan or Report	Completed		12/24/2014
VCP Opinion on Feasibility Study	Completed	4/20/2015	10/6/2015
VCP Receipt of Plan or Report	Completed		7/5/2016
VCP Opinion on Site Cleanup	Completed	7/5/2016	5/25/2017
VCP Receipt of Plan or Report	Completed		7/6/2016
VCP Receipt of Plan or Report	Completed		9/25/2017
VCP Opinion on Site Cleanup Plan	Completed	9/25/2017	10/12/2017
VCP Technical Assistance	Completed		11/2/2017
VCP Opinion on Site Cleanup Plan	Completed	11/3/2017	11/16/2017
VCP Receipt of Plan or Report	Completed		8/7/2018
VCP Opinion on Feasibility Study	Completed	8/7/2018	8/30/2019
VCP Technical Assistance	Completed		10/9/2019
VCP Receipt of Plan or Report	Completed		8/31/2021
VCP Opinion on Feasibility Study	Completed	8/31/2021	10/21/2022
VCP Receipt of Plan or Report	Completed		4/20/2023
VCP Receipt of Plan or Report	Completed		9/10/2024
VCP Technical Assistance	Completed		10/7/2024
SHARP Assessment	Completed		7/1/2025