

## Cleanup Site Details

Cleanup Site ID: 16551

Cleanup Site ID: 16551 Facility/Site ID: 60800 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: BLT Trucking Glossary

Alternate Names: BLT Truck & Trailer Repair LLC, BLT Trucking

LOCATION

 Address:
 8010 S 259TH ST
 City:
 KENT
 Zip Code:
 98032
 County:
 King

Latitude: 47.37026 Longitude: -122.23243 WRIA: 9 Legislative District: 33 Congressional District: 9 TRS: 22N 4E 25

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Vik, Kim Responsible Unit: Northwest Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name Unit Type Unit Status Resp Unit Manager Current Process

BLT Trucking Upland Cleanup Started NW Vik, Kim Standard Voluntary Cleanup

**ACTIVE INSTITUTIONAL CONTROLS** 

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

		MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Arsenic	С	С						
Lead	С	В						
Metals - Other	С	В						
Petroleum-Diesel	С	В						
Petroleum-Other	С	В						
Polychlorinated biPhenyls (PCB)	С	В						

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above

S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		2/23/2022
VCP Receipt of Plan or Report	Completed		2/23/2022
VCP Receipt of Plan or Report	Completed		2/23/2022
VCP Receipt of Plan or Report	Completed		2/23/2022
VCP Opinion on Remedial Investigation	Completed	2/23/2022	3/13/2023

Toxics Cleanup Program Report Generated: 5/27/2025 Page 1 of 2



## Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
VCP Receipt of Plan or Report	Completed		6/14/2022			
VCP Receipt of Plan or Report	Completed		5/3/2023			
VCP Receipt of Plan or Report	Completed		7/30/2024			
VCP Receipt of Plan or Report	Completed		7/30/2024			
VCP Opinion on Remedial Investigation	In Process	7/30/2024				
VCP Receipt of Plan or Report	Completed		7/31/2024			
VCP Receipt of Plan or Report	Completed		9/30/2024			
VCP Technical Assistance	Completed		10/29/2024			
Site Hazard Assessment/Federal Site Inspection	Completed		1/9/2025			

Cleanup Site ID: 16551