

Cleanup Site Details

Cleanup Site ID: 16660

Cleanup Site ID: 16660	Facility/Site ID: 82269249	UST ID: 1627	Site Page	Site Documents	View Map	
Cleanup Site Name: PAPE Machinery Glossary						
Alternate Names: FARMWAY IMPLEMENT CO INC, FARMWAY IMPLEMENT COMPANY INC, Farmway Implement Inc, PAPE, PAPE Machinery, Washington Tractor						
LOCATION						
Address: 731 F ST SE		City: QUINCY	Zip Code: 98848	County: Grant		
Latitude: 47.23383	Longitude: -119.84052	WRIA: 41	Legislative District: 13	Congressional District: 4	TRS: 20N 24E 17	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 8/11/2022	Current VCP? No	Past VCP? No			
Site Rank: N/A	NFA Reason: Initial Investigation	Brownfield? No				
Site Manager: Fulton, Sara	Responsible Unit: Eastern	Active Institutional Control? No				
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
PAPE	Upland	No Further Action Required	EA	Fulton, Sara	Independent Action	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					
Petroleum-Other	RB					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed			6/27/2022		
Initial Investigation / Federal Preliminary Assessment	Completed			8/8/2022		
Site Status Changed to NFA	Completed			8/11/2022		