

Cleanup Site Details

Cleanup Site ID: 16663

Cleanup Site ID: 16663 Facility/Site ID: 19188572 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Midas Muffler Ballard [Glossary](#)

Alternate Names: Midas Auto Service Experts Ballard, Midas Muffler Ballard

LOCATION

Address: 7055 15th Ave NW City: Seattle Zip Code: 98117 County: King
Latitude: 47.68105 Longitude: -122.37713 WRIA: 8 Legislative District: 36 Congressional District: 7 TRS: 25N 3E 2

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Midas Muffler Ballard	Upland	Cleanup Started	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	C	B				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		7/22/2022
VCP Receipt of Plan or Report	Completed		7/26/2022
VCP Opinion on Feasibility Study	Completed	7/26/2022	6/28/2023
Early Notice Letter(s)	Completed		3/23/2023
VCP Status Request	Completed	10/2/2024	11/12/2024