

# Cleanup Site Details

Cleanup Site ID: 16669

Cleanup Site ID: 16669 Facility/Site ID: 15428546 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Pend Oreille Mine Historic Debris Field [Glossary](#)

**Alternate Names:** COMINCO AMERICAN INC, COMINCO AMERICAN INC METALINE FALLS, PEND OREILLE MINE, Pend Oreille Mine Const, Pend Oreille Mine Historic Debris Field, TECK COMINCO

## LOCATION

**Address:** 1382 PEND OREILLE MINES RD **City:** METALINE FALLS **Zip Code:** 99153 **County:** Pend Oreille  
**Latitude:** 48.88179 **Longitude:** -117.36004 **WRIA:** 62 **Legislative District:** 7 **Congressional District:** 5 **TRS:** 39N 43E 15

## DETAIL

**Status:** Cleanup Started **NFA Received?** No **Is PSI site?** No  
**Statute:** MTCA **NFA Date:** N/A **Current VCP?** Yes **Past VCP?** Yes  
**Site Rank:** N/A **NFA Reason:** N/A **Brownfield?** No  
**Site Manager:** Uecker, Ted **Responsible Unit:** Eastern **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Historic Debris Field	Upland	Awaiting Cleanup	EA	Uecker, Ted	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C					
Benzene	C					
Halogenated Pesticides	B					
Halogenated Solvents	C					
Lead	C					
Metals - Other	C					
Methyl tertiary-butyl ether	B					
Petroleum-Other	B					

**Key:**  
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above  
S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/25/2022
VCP Technical Assistance	Completed		8/24/2022

# Cleanup Site Details

Cleanup Site ID: 16669

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Remedial Investigation	Completed	8/24/2022	10/3/2022
VCP Receipt of Plan or Report	Completed		2/21/2023
VCP Opinion on Remedial Investigation Work Plan	Completed	2/21/2023	4/4/2023
VCP Receipt of Plan or Report	Completed		9/23/2024
VCP Opinion on Feasibility Study	Completed	9/23/2024	11/25/2024
VCP Technical Assistance	Completed		2/28/2025