

Cleanup Site Details

Cleanup Site ID: 16669

Cleanup Site ID: 16669 Facility/Site ID: 15428546 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Pend Oreille Mine Historic Debris Field

Glossary

Alternate Names: COMINCO AMERICAN INC, COMINCO AMERICAN INC METALINE FALLS, PEND OREILLE MINE, Pend Oreille Mine Const,

Pend Oreille Mine Historic Debris Field, TECK COMINCO

LOCATION

Address: 1382 PEND OREILLE MINES RD City: METALINE Zip Code: 99153 County: Pend Oreille

FAILS

Latitude: 48.88179 Longitude: -117.36004 WRIA: 62 Legislative District: 7 Congressional District: 5 TRS: 39N 43E 15

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Uecker, Ted Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Historic Debris Field	Upland	Awaiting Cleanup	EA	Uecker, Ted	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	С					
Benzene	С					
Halogenated Pesticides	В					
Halogenated Solvents	С					
Lead	С					
Metals - Other	С					
Methyl tertiary-butyl ether	В					
Petroleum-Other	В					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/25/2022
VCP Technical Assistance	Completed		8/24/2022

Toxics Cleanup Program Report Generated: 11/13/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
VCP Opinion on Remedial Investigation	Completed	8/24/2022	10/3/2022			
VCP Receipt of Plan or Report	Completed		2/21/2023			
VCP Opinion on Remedial Investigation Work Plan	Completed	2/21/2023	4/4/2023			
VCP Receipt of Plan or Report	Completed		9/23/2024			
VCP Opinion on Feasibility Study	Completed	9/23/2024	11/25/2024			
VCP Technical Assistance	Completed		2/28/2025			

Cleanup Site ID: 16669