

## **Cleanup Site Details**

Cleanup Site ID: 16779

Cleanup Site ID: 16779	: 16779 Facility/Site ID: 999991		9999147	47 <b>UST ID</b> : N/A			Site Page			e Docume	<u>View Map</u>		
Cleanup Site Name: Mabana Area PFAS <u>Glossary</u>													
Alternate Names: Mabana Area PFAS													
LOCATION													
Address: 3169 Redwing Rd City: Camano							Zip C	ode: 9828	32	County:	Island		
Latitude: 48.09545	tude: 48.09545 Longitude: -122.41373 WRIA:			Legislative District: 10 Con				ongressio	gressional District: 2 TRS: 30N 3E 10				
DETAIL													
Status: Awaiting Clea	tatus: Awaiting Cleanup NFA Receiv			? No Is						PSI site? No			
Statute: MTCA NFA Date:			Date:	N/A C					urrent VCP? No Past VCP? No				
Site Rank: N/A NFA Reaso				N/A Brownfield? No									
Site Manager: Northwest Region Responsible			onsible Unit:	Northv	vest	Active Institutional Control? No							
CLEANUP UNITS													
Cleanup Unit Name Unit Type			Unit S	Unit Status			Unit Manager			Current Process			
Mabana Area PFAS Upland			Awaiting	Awaiting Cleanup			Wooten, Kim			No Process			
ACTIVE INSTITUTIONAL CONTROLS													
	Iment Type Restriction Media Restrictions/			s/Requirements			Date Recor			g Recording County		Tax Parcel	
There are no current Institutional Controls in effect for this site.													
AFFECTED MEDIA & CONTAMINANTS													
						MEDIA							
Contaminant			Soi	il	Groundwat		Surface	Water	Sedim	ent	Air	Bedrock	
Per- and polyfluoroalkyl substances (PFAS)					S								
Key:     B - Below Cleanup Level   C - Confirmed Above Cleanup Level   RA - Remediated-Above     S - Suspected   R - Remediated   RB - Remediated-Below													
SITE ACTIVITIES													
Activity							Status		Start Date		End Date/ Completion Date		
Site Discovery/Release Report Received						C	Completed				9/1/2022		
Initial Investigation / Federal Preliminary Assessment							Completed			3/15/2023			