DEPARTMENT OF ECOLOGY
State of Washington

Cleanup Site Details

Cleanup Site ID: 16779

Cleanup Site ID: 16779 **Facility/Site ID:** 99999147 **UST ID:** N/A Site Page | Site Documents | View Map

Cleanup Site Name: Mabana Area PFAS Glossary

Alternate Names: Mabana Area PFAS

LOCATION

Address: 3169 Redwing Rd **City:** Camano Island **Zip Code:** 98282 **County:** Island

Latitude: 48.09545 **Longitude:** -122.41373 **WRIA:** 6 **Legislative District:** 10 **Congressional District:** 2 **TRS:** 30N 3E 10

DETAIL

Status: Awaiting Cleanup **NFA Received?** No **Is PSI site?** No

Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No

Site Manager: Northwest Region **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Mabana Area PFAS	Upland	Awaiting Cleanup	NW	Wooten, Kim	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	**Soil**	**Groundwater**	**Surface Water**	**Sediment**	**Air**	**Bedrock**
Per- and polyfluoroalkyl substances (PFAS)		S				

Key:
B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated
RA - Remediated-Above
RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/1/2022
Initial Investigation / Federal Preliminary Assessment	Completed		3/15/2023