

# Cleanup Site Details

Cleanup Site ID: 16779

<b>Cleanup Site ID:</b> 16779	<b>Facility/Site ID:</b> 99999147	<b>UST ID:</b> N/A	<a href="#">Site Page</a>	<a href="#">Site Documents</a>	<a href="#">View Map</a>
<b>Cleanup Site Name:</b> Mabana Area PFAS					<a href="#">Glossary</a>
<b>Alternate Names:</b> Mabana Area PFAS					

## LOCATION

<b>Address:</b> 3169 Redwing Rd			<b>City:</b> Camano Island	<b>Zip Code:</b> 98282	<b>County:</b> Island
<b>Latitude:</b> 48.09545	<b>Longitude:</b> -122.41373	<b>WRIA:</b> 6	<b>Legislative District:</b> 10	<b>Congressional District:</b> 2	<b>TRS:</b> 30N 3E 10

## DETAIL

<b>Status:</b> Awaiting Cleanup	<b>NFA Received?</b> No	<b>Is PSI site?</b> No
<b>Statute:</b> MTCA	<b>NFA Date:</b> N/A	<b>Current VCP?</b> No <b>Past VCP?</b> No
<b>Site Rank:</b> N/A	<b>NFA Reason:</b> N/A	<b>Brownfield?</b> No
<b>Site Manager:</b> Northwest Region	<b>Responsible Unit:</b> Northwest	<b>Active Institutional Control?</b> No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Mabana Area PFAS	Upland	Awaiting Cleanup	NW	Wooten, Kim	No Process

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Per- and polyfluoroalkyl substances (PFAS)		S				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected                  R - Remediated                  RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/1/2022
Initial Investigation / Federal Preliminary Assessment	Completed		3/15/2023