

Cleanup Site Details

Cleanup Site ID: 16781

Cleanup Site ID: 16781	Facility/Site ID: 99999153	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Deer Lake Area PFAS					Glossary
Alternate Names: Deer Lake Area PFAS					

LOCATION

Address: 6362 Cedar Cove Ln	City: Clinton	Zip Code: 98236	County: Island
Latitude: 47.97928	Longitude: -122.38154	WRIA: 6	Legislative District: 10
		Congressional District: 2	TRS: 29N 3E 23

DETAIL

Status: Awaiting Cleanup	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Deer Lake Area PFAS	Upland	Awaiting Cleanup	NW	Wooten, Kim	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Per- and polyfluoroalkyl substances (PFAS)		S				
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/1/2022
Initial Investigation / Federal Preliminary Assessment	Completed		3/15/2023