

Cleanup Site Details

Cleanup Site ID: 16781

Cleanup Site ID: 16781 Facility/Site ID: 99999153 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Deer Lake Area PFAS

[Glossary](#)

Alternate Names: Deer Lake Area PFAS

LOCATION

Address: 6362 Cedar Cove Ln City: Clinton Zip Code: 98236 County: Island
Latitude: 47.97928 Longitude: -122.38154 WRIA: 6 Legislative District: 10 Congressional District: 2 TRS: 29N 3E 23

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Deer Lake Area PFAS	Upland	Awaiting Cleanup	NW	Wooten, Kim	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Per- and polyfluoroalkyl substances (PFAS)		S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/1/2022
Initial Investigation / Federal Preliminary Assessment	Completed		3/15/2023