

Cleanup Site ID: 16781

Cleanup Site Details

Facility/Site ID: 99999153 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 16781

Cleanup Site Name: Deer Lake Area PFAS Glossary

Alternate Names: Deer Lake Area PFAS

LOCATION

Address: 6362 Cedar Cove Ln City: Clinton Zip Code: 98236 County: Island

Latitude: 47.97928 Longitude: -122.38154 WRIA: 6 Legislative District: 10 Congressional District: 2 TRS: 29N 3E 23

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Deer Lake Area PFAS
 Upland
 Awaiting Cleanup
 NW
 Wooten, Kim
 No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

 MEDIA

 Contaminant
 Soil
 Groundwater
 Surface Water
 Sediment
 Air
 Bedrock

 Per- and polyfluoroalkyl substances (PFAS)
 S
 S
 S

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

ActivityStatusStart DateEnd Date/Completion DateSite Discovery/Release Report ReceivedCompleted9/1/2022Initial Investigation / Federal Preliminary AssessmentCompleted3/15/2023

Toxics Cleanup Program Report Generated: 10/23/2025 Page 1 of 1