

Cleanup Site Details

Cleanup Site ID: 1682

Cleanup Site ID: 1682	Facility/Site ID: 88271495	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Fujicolor Processing Inc					Glossary
Alternate Names: FUJI TRU COLOR TUKWILA, Fujicolor Processing Inc					

LOCATION

Address: 770 ANDOVER PARK E			City: TUKWILA	Zip Code: 98188	County: King
Latitude: 47.45013	Longitude: -122.25077	WRIA: 9	Legislative District: 11	Congressional District: 9	TRS: 23N 4E 26

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 7/12/2005	Current VCP? No Past VCP? Yes
Site Rank: N/A	NFA Reason: Initial Investigation	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Fujicolor Processing Inc	Upland	No Further Action Required	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	B					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		2/7/2005
VCP Opinion on Cleanup Action	Completed	2/7/2005	7/12/2005
Site Status Changed to NFA	Completed		7/12/2005
Initial Investigation / Federal Preliminary Assessment	Completed		7/12/2005