# Cleanup Site Details

**Cleanup Site ID: 16890**

**Cleanup Site ID:** 16890 **Facility/Site ID:** 100000196 **UST ID:** N/A Site Page Site Documents View Map

**Cleanup Site Name:** Naval Outlying Field Glossary

**Alternate Names:** Naval Outlying Field

## LOCATION

**Address:** 18025 State Route 20 **City:** Coupeville **Zip Code:** 98239 **County:** Island

**Latitude:** 48.19399 **Longitude:** -122.63076 **WRIA:** 6 **Legislative District:** 10 **Congressional District:** 2 **TRS:** 31N 1E 12

## DETAIL

**Status:** Awaiting Cleanup **NFA Received?** No **Is PSI site?** No

**Statute:** MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No

**Site Rank:** N/A **NFA Reason:** N/A **Brownfield?** No

**Site Manager:** Chaudhary, Binod **Responsible Unit:** Headquarters **Active Institutional Control?** No

## CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|---|---|---|---|---|---|
| Naval Outlying Field | Upland | Awaiting Cleanup | HQ | Chaudhary, Binod | Ecology-supervised or conducted |

## ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|---|---|---|---|---|---|---|
| There are no current Institutional Controls in effect for this site. | | | | | | |

## AFFECTED MEDIA & CONTAMINANTS

| | MEDIA | | | | | |
|---|---|---|---|---|---|---|
| **Contaminant** | **Soil** | **Groundwater** | **Surface Water** | **Sediment** | **Air** | **Bedrock** |
| Per- and polyfluoroalkyl substances (PFAS) | | C | | | | |

**Key:**
B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated
RA - Remediated-Above
RB - Remediated-Below

## SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|---|---|---|---|
| Site Discovery/Release Report Received | Completed | | 9/1/2022 |