

# Cleanup Site Details

Cleanup Site ID: 16913

Cleanup Site ID: 16913      Facility/Site ID: 70525886      UST ID: 5073      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Stillwater Holdings Chevron      [Glossary](#)

Alternate Names: BILL SINGERS CHEVRON, SINGERS CHEVRON FOOD MART, Stillwater Holdings Chevron, Wine Country Store

## LOCATION

Address: 7 E Rose Street      City: WALLA WALLA      Zip Code: 99362      County: Walla Walla  
Latitude: 46.06791      Longitude: -118.33986      WRIA: 32      Legislative District: 16      Congressional District: 5      TRS: 7N 36E 20

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: Kercher, Beth      Responsible Unit: Eastern      Active Institutional Control? Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Wine Country Store	Upland	Cleanup Started	EA	Kercher, Beth	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Restrict Land Use, Prohibit Soil Disturbance, Prevent the Reuse or Relocation of Site Soil	5/17/2013	2013-04956	Walla Walla	360720574707

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C					
Other Non-Halogenated Organics	C					
Petroleum-Gasoline	C	C			C	

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/14/2023
LUST - Notification	Completed		9/14/2023
LUST - Report Received	Completed		10/11/2023
LUST - Report Received	Completed		10/26/2023
LUST - Site Assessment Report	Completed		11/10/2023
LUST - Report Received	Completed		11/17/2023
LUST - Report Received	Completed		12/28/2023

# Cleanup Site Details

Cleanup Site ID: 16913

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
30-Day Notice of PLP Status	Completed	1/18/2024	6/18/2024
LUST - Report Received	Completed		2/7/2024
Order/Decree/Amendment	Canceled	2/29/2024	5/9/2024
LUST - Report Received	Completed		3/27/2024
LUST - Report Received	Completed		3/28/2024
LUST - Report Received	Completed		5/8/2024
LUST - Site Assessment Report	Completed		6/4/2024
Property Access Agreement	Completed	6/5/2024	3/5/2025
Order/Decree/Amendment	In Process	6/18/2024	
Order/Decree/Amendment	In Process	6/18/2024	
Property Access Agreement	Completed	9/6/2024	1/23/2025
Property Access Agreement	Completed	1/30/2025	2/28/2025
LUST - Report Received	Completed		2/4/2025