

# Cleanup Site Details

Cleanup Site ID: 16913

**Cleanup Site ID:** 16913      **Facility/Site ID:** 70525886      **UST ID:** 5073      [Site Page](#)      [Site Documents](#)      [View Map](#)  
**Cleanup Site Name:** Stillwater Holdings Chevron      [Glossary](#)  
**Alternate Names:** BILL SINGERS CHEVRON, SINGERS CHEVRON FOOD MART, Stillwater Holdings Chevron, Wine Country Store

**LOCATION**

**Address:** 7 E Rose Street      **City:** WALLA WALLA      **Zip Code:** 99362      **County:** Walla Walla  
**Latitude:** 46.06791      **Longitude:** -118.33986      **WRIA:** 32      **Legislative District:** 16      **Congressional District:** 5      **TRS:** 7N 36E 20

**DETAIL**

**Status:** Awaiting Cleanup      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** N/A      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Kercher, Beth      **Responsible Unit:** Eastern      **Active Institutional Control?** Yes

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Wine Country Store	Upland	Awaiting Cleanup	EA	Kercher, Beth	Ecology-supervised or conducted

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Restrict Land Use, Prohibit Soil Disturbance, Prevent the Reuse or Relocation of Site Soil	5/17/2013	2013-04956	Walla Walla	360720574707

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

**AFFECTED MEDIA & CONTAMINANTS**

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C					
Other Non-Halogenated Organics	C					
Petroleum-Gasoline	C	C			C	

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
30-Day Notice of PLP Status	Completed		
Property Access Agreement	Completed		
Property Access Agreement	In Process		
Site Discovery/Release Report Received	Completed		9/14/2023
LUST - Notification	Completed		9/14/2023
LUST - Report Received	Completed		10/11/2023
LUST - Report Received	Completed		10/26/2023

# Cleanup Site Details

Cleanup Site ID: 16913

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Site Assessment Report	Completed		11/10/2023
LUST - Report Received	Completed		11/17/2023
LUST - Report Received	Completed		12/28/2023
LUST - Report Received	Completed		2/7/2024
LUST - Report Received	Completed		3/27/2024
LUST - Report Received	Completed		3/28/2024
LUST - Report Received	Completed		5/8/2024
LUST - Site Assessment Report	Completed		6/4/2024
LUST - Report Received	Completed		2/4/2025