

Cleanup Site Details

Cleanup Site ID: 16913

Cleanup Site ID: 16913 **Facility/Site ID:** 70525886 **UST ID:** 5073 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Stillwater Holdings Chevron [Glossary](#)
Alternate Names: BILL SINGERS CHEVRON, SINGERS CHEVRON FOOD MART, Stillwater Holdings Chevron, Wine Country Store

LOCATION

Address: 7 E Rose Street **City:** WALLA WALLA **Zip Code:** 99362 **County:** Walla Walla
Latitude: 46.06791 **Longitude:** -118.33986 **WRIA:** 32 **Legislative District:** 16 **Congressional District:** 5 **TRS:** 7N 36E 20

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Kercher, Beth **Responsible Unit:** Eastern **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Wine Country Store	Upland	Cleanup Started	EA	Kercher, Beth	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Restrict Land Use, Prohibit Soil Disturbance, Prevent the Reuse or Relocation of Site Soil	5/17/2013	2013-04956	Walla Walla	360720574707

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C					
Other Non-Halogenated Organics	C					
Petroleum-Gasoline	C	C			C	

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
30-Day Notice of PLP Status	Completed		
Property Access Agreement	Completed		
Property Access Agreement	Completed		
Property Access Agreement	Completed		
Site Discovery/Release Report Received	Completed		9/14/2023
LUST - Notification	Completed		9/14/2023
LUST - Report Received	Completed		10/11/2023

Cleanup Site Details

Cleanup Site ID: 16913

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		10/26/2023
LUST - Site Assessment Report	Completed		11/10/2023
LUST - Report Received	Completed		11/17/2023
LUST - Report Received	Completed		12/28/2023
LUST - Report Received	Completed		2/7/2024
Order/Decree/Amendment	Canceled	2/29/2024	5/9/2024
LUST - Report Received	Completed		3/27/2024
LUST - Report Received	Completed		3/28/2024
LUST - Report Received	Completed		5/8/2024
LUST - Site Assessment Report	Completed		6/4/2024
Order/Decree/Amendment	In Process	6/18/2024	
Order/Decree/Amendment	In Process	6/18/2024	
LUST - Report Received	Completed		2/4/2025