	DEPARTMENT OF						
	ECOLOGY						
	State of Washington						

## **Cleanup Site Details**

Cleanup Site ID: 17012

Cleanup Site ID: 1	7012 <b>Faci</b>	lity/Site ID: 1	00000762	762 <b>UST ID:</b> N/A		Site P	Site Page Site Docum			<u>View Map</u>		
Cleanup Site Name: Baurs Greenhouse												
Alternate Names: Baurs Greenhouse, Cottage Hill Place												
LOCATION												
Address: 1501 Fol	som Ave			City: Yakima		Zip Code: 98902 Cour			<b>ty:</b> Yakima			
Latitude: 46.60246	Longitude: -	120.52858	WRIA: 37	Legislative District:		14 Congres	ssional I	TRS:	13N 18E 24			
DETAIL												
Status: Cleanup	us: Cleanup Started NFA Received? No			Is PSI site? No								
Statute: MTCA		NFA	Date:	N/A		Current VCP? Yes Past VCP? Yes						
Site Rank: N/A	Site Rank: N/A NFA Reason: N/A				Brownfield? No							
Site Manager: Care	Site Manager: Caron, Rachel Responsible Unit: Central Active Institutional Control						Control?	No				
CLEANUP UNITS												
Cleanup U	nit Name	Unit Type	Unit	Status	Resp Unit	Unit Manag	ger	Current Process				
Baurs Greenhouse		Upland	Cleanup Started		CE	Caron, Rac	hel	Standard Voluntary Cleanup				
ACTIVE INSTITUTIONAL CONTROLS												
Instrument Type	Restriction Media	Restr	rictions/Requirements			Date Recordi Numbe		Record Cour		Tax Parcel		
There are no current Institutional Controls in effect for this site.												
AFFECTED MEDIA & CONTAMINANTS												
						ME	DIA					
Contaminant			So		water	Surface Wate	er Sediment		Air	Bedrock		
Halogenated Pesticides C S												
Key:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below												
SITE ACTIVITIES												
Activity						Status	Star	rt Date		nd Date/ pletion Date		
Site Discovery/Release Report Received					С	Completed			2/15/2024			
Initial Investigation / Federal Preliminary Assessment					C	Completed			3/7/2024			
Early Notice Letter(s)					С	Completed			4/2/2024			
SHARP Assessment					C	Completed			6/	27/2024		