ECOLOGY State of Washington	leanu	o Site I	Deta	ails		Clea	anup Site	ə ID: 17021	
Cleanup Site ID: 17021 Facility/Site ID: 439	UST ID: 101	IST ID: 101627 Site Page			Site Documents View Map				
Cleanup Site Name: SCL North Substation Landscap	ng							<u>Glossary</u>	
Alternate Names: NORTH SUBSTATION, SCL North	Substation, S	CL North Subs	tation L	andscaping	g, Seattle Cit	y North Su	bstation		
LOCATION									
Address: 7500 8th Ave NE City: Seattle			Zip Code: 98115 County: King						
Latitude: 47.68369 Longitude: -122.31947 WF	IA: 8	Legislative D	strict:	46 Co	ngressional	District:	7 TRS:	25N 4E 5	
DETAIL									
Status: Awaiting Cleanup NFA Red	NFA Received? No			Is PSI site? No					
Statute: MTCA NFA Dat	NFA Date: N/A			Current VCP? No Past VCP? No					
Site Rank: N/A NFA Rea	NFA Reason: N/A			Brownfield? No					
ite Manager: Northwest Region Responsible Unit: Northwest			Active Institutional Control? No						
CLEANUP UNITS									
Cleanup Unit Name Unit Type	Unit Status		Resp Unit	Unit Manager		Current Process			
SCL North Substation Landscaping Upland	Awaiting (NW	Northwest Region		Independent Action				
ACTIVE INSTITUTIONAL CONTROLS									
Instrument Type Restriction Restrict	Restrictions/Requirements			Date	Recording Number		ording unty	Tax Parcel	
nere are no current Institutional Controls in effect for this site.									
AFFECTED MEDIA & CONTAMINANTS									
					MEDIA				
Contaminant	Soil	Ground	water	Surface	Water Se	diment	Air	Bedrock	
Halogenated Pesticides	C							ļ	
Lead	C								
Key: B - Below Cleanup Level C - Confirmed Above C S - Suspected R - Remediated	leanup Level	RA - Rem RB - Rem							
SITE ACTIVITIES									
Activity				Status		art Date	End Date/ Completion Date		
Site Discovery/Release Report Received				Completed			9/26/2017		
Initial Investigation / Federal Preliminary Assessment				Completed			1	1/30/2024	
SHARP Assessment				Completed			3/14/2024		
SHARP Assessment			(ompieted				/14/2024	