

Cleanup Site Details

Cleanup Site ID: 17023

Cleanup Site ID: 17023 Facility/Site ID: 100001640 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Boundary Dam Vista House [Glossary](#)

Alternate Names: Boundary Dam Vista House

LOCATION

Address: 2001 Eastside Access Rd **City:** Metaline Falls **Zip Code:** 99153 **County:** Pend Oreille
Latitude: 48.98948 **Longitude:** -117.34701 **WRIA:** 62 **Legislative District:** 7 **Congressional District:** 5 **TRS:** 40N 43E 3

DETAIL

Status: Awaiting Cleanup	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Rice, Justin	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Boundary Dam Vista House	Upland	Awaiting Cleanup	CE	Rice, Justin	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C					
Lead	C					
Mercury	C					
Metals - Other	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		4/10/2024