

Cleanup Site Details

Cleanup Site ID: 17025

Cleanup Site ID: 1702	5 Facil i	ity/Site ID:	100001666	UST ID: N	/A		Site Page	Site Docur	<u>ments</u>	<u>View Map</u>	
Cleanup Site Name: Crow Property Glossary											
Alternate Names: Crow Property											
LOCATION											
Address: Hwy 14 City: Pate					son	n Zip Code: 99345 County: Benton					
Latitude: 45.93490	atitude: 45.93490 Longitude: -119.60374 WRIA:			Legislative District: 16			Congressional District: 4 TRS: 5N 26E 7				
DETAIL											
Status: Awaiting Cleanup NFA Receiv			Received?	No Is PSI site? No							
Statute: MTCA NFA Date:			Date:	N/A Current VCP? No Past VCP?					VCP? No		
Site Rank: N/A NFA Reaso			Reason:	N/A	N/A Brownfield? No						
Site Manager: Central Region Responsible			onsible Unit:	Central		Active Institutional Control? No					
CLEANUP UNITS											
Cleanup Unit Name Unit Type			Unit	Unit Status		Unit Manager		Current Process			
Crow Property Upland			Awaiting	g Cleanup	CE	Central Region			No Process		
ACTIVE INSTITUTIONAL CONTROLS											
Instrument Type	Instrument Type Restriction Restriction			ons/Requirements			Recording Number		ording Tax Parcel		
There are no current Institutional Controls in effect for this site.											
AFFECTED MEDIA & CONTAMINANTS											
						MEDIA					
Contaminant			So So	il Grou	Groundwater		Water Se	ediment	Air	Bedrock	
Petroleum-Other											
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below											
SITE ACTIVITIES											
Activity						Status				d Date/ letion Date	
Site Discovery/Release Report Received						Completed			7/	7/11/2022	
Initial Investigation / Federal Preliminary Assessment						Completed			2/13/2024		