

Cleanup Site Details

Cleanup Site ID: 17026

Cleanup Site ID: 17026 Facility/Site ID: 67389 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: BNSF Finley Track Spill [Glossary](#)

Alternate Names: BNSF Finley Track Spill, BNSF Railroad near Hanover Park - Cushman Siding

LOCATION

Address: City: Zip Code: 99337 County: Benton
Latitude: 46.12347 Longitude: -118.99085 WRIA: 31 Legislative District: 16 Congressional District: 4 TRS: 7N 31E 6

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
BNSF Finley Track Spill	Upland	Awaiting Cleanup	CE	Central Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C		S			

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		12/8/1991
Initial Investigation / Federal Preliminary Assessment	Completed		2/13/2024