

# Cleanup Site Details

Cleanup Site ID: 17032

Cleanup Site ID: 17032      Facility/Site ID: 7831067      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Burrows Island Light Station      [Glossary](#)

Alternate Names: Burrows Island Light Station

## LOCATION

Address: BURROWS ISLAND      City: ANACORTES      Zip Code: 98221      County: Skagit  
Latitude: 48.47928      Longitude: -122.70022      WRIA: 3      Legislative District: 10      Congressional District: 2      TRS: 35N 1E 33

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: Federal - CERCLA      NFA Date: 7/1/2024      Current VCP? No      Past VCP? No  
Site Rank: N/A      NFA Reason: Federal Supervised/Conducted Cleanup      Brownfield? No  
Site Manager: Horne, David      Responsible Unit: Headquarters      Active Institutional Control? No

## CLEANUP UNITS

| Cleanup Unit Name            | Unit Type | Unit Status                | Resp Unit | Unit Manager | Current Process                 |
|------------------------------|-----------|----------------------------|-----------|--------------|---------------------------------|
| Burrows Island Light Station | Upland    | No Further Action Required | HQ        | Horne, David | Federal-supervised or conducted |

## ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

| MEDIA                           |      |             |               |          |     |         |
|---------------------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant                     | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Lead                            | RB   |             |               |          |     |         |
| Petroleum-Diesel                | RB   |             |               |          |     |         |
| Petroleum-Other                 | RB   |             |               |          |     |         |
| Polychlorinated biPhenyls (PCB) | RB   |             |               |          |     |         |

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

| Activity                               | Status    | Start Date | End Date/ Completion Date |
|--|-----------|------------|---------------------------|
| Site Discovery/Release Report Received | Completed |            | 9/26/2023                 |
| Site Status Changed to NFA             | Completed |            | 7/1/2024                  |