State of Washington	F / n	Cl	eanu	ip Site [	Deta	ails		Cle	anup Si	te ID: 17040
Cleanup Site ID: 17	040 Facili	ity/Site ID: 10000	)1955	UST ID: N/A			Site Page	Site Doc	uments	<u>View Map</u>
Cleanup Site Name:	Lawrence Oil Pe	etroleum Spill								<u>Glossary</u>
Alternate Names: L	awrence Oil Petro	oleum Spill, Lawer	ance Oil P	etroleum Spill						
LOCATION										
Address: Highway 24, MP 68			City: Othello			Zip C	Zip Code: County: Franklin			
Latitude: 46.73745	Longitude: -1	19.31284 WRI	<b>A:</b> 36	Legislative D	strict:	9 <b>C</b>	ongression	al District:	4 TRS	<b>3:</b> 14N 28E 4
DETAIL										
Status: No Furthe	er Action	NFA Rece	ived?	Yes			ls PS	l site?	No	
Statute: MTCA NFA		NFA Date	<b>Date:</b> 6/17/20		Ci			ent VCP?	No Pa	st VCP? No
Site Rank: N/A NFA		NFA Reas	Reason: Initial Investigat		tion	Brownfield?			No	
Site Manager: Eastern Region		Responsi	ble Unit:	Eastern	ıstern		Active Institutional Control? No			No No
CLEANUP UNITS										
Cleanup Unit Name Unit T		Unit Type	Unit S	Status	Resp Unit	Unit	Unit Manager		Current Process	
Lawerance Oil Fuel Spill Up		Upland No	No Further Action Required		EA	Easte	ern Region		Independent Action	
ACTIVE INSTITUTIO	NAL CONTROLS									
Instrument Type Restriction Rest			rictions/Requirements			Date Recordin		na Rec	ording	
	weala	Resulctio	ns/Requir	rements		Date	Numbe		ounty	Tax Parcel
There are no current l			•	rements		Date				Tax Parcel
There are no current I	Institutional Contro	ols in effect for this	•	rements		Date				Tax Parcel
	Institutional Contro	ols in effect for this	•	rements		Date				Tax Parcel
AFFECTED MEDIA 8 Contaminant	Institutional Contro	ols in effect for this	s site.	il Ground		Surface	Numbe			Tax Parcel Bedrock
AFFECTED MEDIA 8 Contaminant Petroleum-Diesel	Institutional Contro	ols in effect for this	s site.	il Ground			Numbe	r Cı	ounty	
AFFECTED MEDIA 8 Contaminant Petroleum-Diesel Petroleum-Gasoline	Institutional Contro	ols in effect for this	s site.	il Ground			Numbe	r Cı	ounty	
AFFECTED MEDIA 8 Contaminant	Institutional Contro	ols in effect for this	s site.	il Ground	water	Surface -Above	Numbe	r Cı	ounty	
AFFECTED MEDIA 8 Contaminant Petroleum-Diesel Petroleum-Gasoline Key: B - Below Cleanup Le S - Suspected	Institutional Contro	ols in effect for this	s site.	il Ground 3 3	water	Surface -Above	Numbe	r Cı	ounty	
AFFECTED MEDIA 8 Contaminant Petroleum-Diesel Petroleum-Gasoline Key: B - Below Cleanup Le S - Suspected SITE ACTIVITIES	Institutional Contro	ols in effect for this	s site.	il Ground 3 3	water	Surface -Above	MEDIA Water S	r Cı	Air	
AFFECTED MEDIA 8 Contaminant Petroleum-Diesel Petroleum-Gasoline Key: B - Below Cleanup Le	evel C - Con R - Ren	ols in effect for this 'S hfirmed Above Cle nediated	s site.	il Ground 3 3	water ediated	-Above -Below	Numbe	Sediment	Air	Bedrock
AFFECTED MEDIA 8 Contaminant Petroleum-Diesel Petroleum-Gasoline Key: B - Below Cleanup Le S - Suspected SITE ACTIVITIES Activity	evel C - Con R - Ren	ols in effect for this	s site.	il Ground 3 3	ediated ediated	-Above -Below Status	Numbe	Sediment	Air	End Date/ mpletion Date