

Cleanup Site ID: 17053

Cleanup Site Details

Facility/Site ID: 100001668 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 17053

Cleanup Site Name: Kendrick Landing Glossary

Alternate Names: Kendrick Landing

LOCATION

Address: 4610 114th St SW City: Lakewood Zip Code: 98499 County: Pierce

Latitude: 47.15457 Longitude: -122.49881 WRIA: 12 Legislative District: 29 Congressional District: 10 TRS: 19N 2E 12

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 10/3/2024 Current VCP? No Past VCP? Yes

Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Mullin, Tim Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Soil
 Upland
 No Further Action Required
 SW
 Mullin, Tim
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Arsenic	RB						
Other Non-Halogenated Organics	RB						
Petroleum-Diesel	RB						

Key:

B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		7/15/2024
VCP Receipt of Plan or Report	Completed		7/15/2024
VCP Opinion on Site Cleanup	Completed	7/15/2024	10/3/2024
Site Status Changed to NFA	Completed		10/3/2024

Toxics Cleanup Program Report Generated: 6/30/2025 Page 1 of 1