

## Cleanup Site Details

Cleanup Site ID: 17075 Facility/Site ID: 100002581 UST ID: N/A Site Page Site Documents View Map

Cleanup Site ID: 17075

Cleanup Site Name: Marcelas Cocina Mexicana Glossary

Alternate Names: Marcelas Cocina Mexicana

LOCATION

Address: 119 E Woodin Ave City: Chelan Zip Code: 98816 County: Chelan

Latitude: 47.84037 Longitude: -120.01820 WRIA: 47 Legislative District: 12 Congressional District: 8 TRS: 27N 22E 13

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Marcelas Cocina Mexicana	Upland	Awaiting Cleanup	CE	Central Region	No Process

## **ACTIVE INSTITUTIONAL CONTROLS**

l	Instrument Type	Restriction	Restrictions/Requirements	Date	Recording Recording		Tax Parcel
ı	mstrument Type	Media	ixestrictions/ixequirements	Date	Number	County	Tax Faicei

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	В						
Non-Halogenated Solvents	В						
Petroleum-Diesel	С						
Petroleum-Gasoline	В						
Petroleum-Other	В						

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		2/16/2022
Non-LUST Ind Report Received	Completed		6/22/2022

Toxics Cleanup Program Report Generated: 7/3/2025 Page 1 of 1