

Cleanup Site Details

Cleanup Site ID: 17086

Cleanup Site ID: 17086 Facility/Site ID: 94766722 UST ID: 6270 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Pier 66 Sediments [Glossary](#)

Alternate Names: BELL ST TERMINAL PIER 66, Pier 66 Sediments, Port of Seattle Pier 66 LUST, Seattle Port Term 66

LOCATION

Address: 2201 Alaskan Way City: Seattle Zip Code: 98121 County: King
Latitude: 47.61079 Longitude: -122.34822 WRIA: 8 Legislative District: 36 Congressional District: 7 TRS:

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Pier 66 Sediments	Sediment	Awaiting Cleanup	NW	Northwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Dioxins/Furans				C		
Lead				S		
Mercury				C		
Metals - Other				S		
Polychlorinated biPhenyls (PCB)				C		
Polycyclic Aromatic Hydrocarbons				C		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/13/1990
SHARP Assessment	Completed		2/6/2025
Early Notice Letter(s)	Completed		3/4/2025