

Cleanup Site Details

Cleanup Site ID: 17091

Cleanup Site ID: 17091 Facility/Site ID: 100002686 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Yesler Way Chevron

[Glossary](#)

Alternate Names: Yesler Way Chevron

LOCATION

Address: 101 107 27th Ave City: Seattle Zip Code: 98122 County: King
Latitude: 47.60192 Longitude: -122.29816 WRIA: 8 Legislative District: 37 Congressional District: 9 TRS: 24N 4E 4

DETAIL

Status: Awaiting Cleanup	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: N/A	Brownfield? No
Site Manager: Northwest Region	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Yesler Way Chevron	Upland	Awaiting Cleanup	NW	Northwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Other Non-Halogenated Organics	C	C				
Petroleum-Diesel	C					
Petroleum-Gasoline	C	C				
Petroleum-Other	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/9/2024
Early Notice Letter(s)	Completed		3/5/2025