

# Cleanup Site Details

Cleanup Site ID: 17091

Cleanup Site ID: 17091      Facility/Site ID: 100002686      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Yesler Way Chevron

[Glossary](#)

Alternate Names: Yesler Way Chevron

## LOCATION

**Address:** 101 107 27th Ave      **City:** Seattle      **Zip Code:** 98122      **County:** King  
**Latitude:** 47.60192      **Longitude:** -122.29816      **WRIA:** 8      **Legislative District:** 37      **Congressional District:** 9      **TRS:** 24N 4E 4

## DETAIL

<b>Status:</b> Awaiting Cleanup	<b>NFA Received?</b> No	<b>Is PSI site?</b> No
<b>Statute:</b> MTCA	<b>NFA Date:</b> N/A	<b>Current VCP?</b> No <b>Past VCP?</b> No
<b>Site Rank:</b> N/A	<b>NFA Reason:</b> N/A	<b>Brownfield?</b> No
<b>Site Manager:</b> Northwest Region	<b>Responsible Unit:</b> Northwest	<b>Active Institutional Control?</b> No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Yesler Way Chevron	Upland	Awaiting Cleanup	NW	Northwest Region	Independent Action

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C				
Other Non-Halogenated Organics	C	C				
Petroleum-Diesel	C					
Petroleum-Gasoline	C	C				
Petroleum-Other	C					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/9/2024
Early Notice Letter(s)	Completed		3/5/2025