

Cleanup Site Details

Cleanup Site ID: 17109

Cleanup Site ID: 17109 Facility/Site ID: 100002960 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Baxter South Woodwaste Landfill [Glossary](#)

Alternate Names: Baxter South Woodwaste Landfill

LOCATION

Address: 6520 188th St NE City: Arlington Zip Code: 98223 County: Snohomish
Latitude: 48.16393 Longitude: -122.14491 WRIA: 7 Legislative District: 39 Congressional District: 2 TRS: 31N 5E 22

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: O'Connor, Tim Responsible Unit: Solid Waste Program Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Baxter South Woodwaste Landfill	Upland	Awaiting Cleanup	SWP	Noell, Alan	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Metals - Other		C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/1/2021
Initial Investigation / Federal Preliminary Assessment	Completed		6/4/2024
SHARP Assessment	Completed		6/4/2024
Early Notice Letter(s)	Completed		2/11/2025