

# Cleanup Site Details

Cleanup Site ID: 17113

Cleanup Site ID: 17113      Facility/Site ID: 6512294      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Baxter North Woodwaste Landfill      [Glossary](#)

Alternate Names: Baxter North Woodwaste Landfill

## LOCATION

Address: NW of 67th Ave NE & 197th St NE      City: Arlington      Zip Code: 98223      County: Snohomish  
Latitude: 48.17617      Longitude: -122.14347      WRIA: 5      Legislative District: 39      Congressional District: 2      TRS: 31N 5E 15

## DETAIL

Status: Awaiting Cleanup      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: N/A      NFA Reason: N/A      Brownfield? No  
Site Manager: O'Connor, Tim      Responsible Unit: Solid Waste Program      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Baxter North Woodwaste Landfill	Upland	Awaiting Cleanup	SWP	Noell, Alan	Independent Action

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic		C				
Metals - Other		C				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/1/2021
Initial Investigation / Federal Preliminary Assessment	Completed		6/11/2024
SHARP Assessment	Completed		6/11/2024
Early Notice Letter(s)	Completed		2/11/2025