

# Cleanup Site Details

Cleanup Site ID: 17135

Cleanup Site ID: 17135      Facility/Site ID: 100003126      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: First Christian Church HOT      [Glossary](#)

Alternate Names: First Christian Church HOT

## LOCATION

Address: 404 NE 6th Ave      City: Camas      Zip Code: 98607      County: Clark  
Latitude: 45.58704      Longitude: -122.40474      WRIA: 28      Legislative District: 18      Congressional District: 3      TRS: 1N 3E 47

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 5/1/2024      Current VCP? No      Past VCP? No  
Site Rank: N/A      NFA Reason: Initial Investigation      Brownfield? No  
Site Manager: Southwest Region      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
First Christian Church HOT	Upland	No Further Action Required	SW	Southwest Region	Independent Action

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/7/2023
Initial Investigation / Federal Preliminary Assessment	Completed		5/1/2024
Site Status Changed to NFA	Completed		5/1/2024