| Cleanup Site ID: 1 | | | | | | | | | | D: 17149 | | |
|---|----------|----------------------|---------------------------------|-------------|--------------------|--------------|---------------|---------------------------|------------|-----------------|--|--|
| Cleanup Site ID: 17149 Facility/Site ID: 94602 | | 02 | UST ID: 525 | | Site Page | | e <u>Site</u> | Site Documents | | <u>View Map</u> | | |
| Cleanup Site Name: Centralia City L | | | | | | | | <u>Glossary</u> | | | | |
| Alternate Names: Centralia City Light Transformer Spill, Centralia City of Light Department, City of Centralia Light Department | | | | | | | | | | | | |
| LOCATION | | | | | | | | | | | | |
| Address: 1100 N TOWER AVE | | | City: CENTRALIA Zip Code: 98531 | | | | 531 | 1 County: Lewis | | | | |
| Latitude: 46.72831 Longitude: -122.95152 WRIA: 23 Legislative District: 20 Congressional District: 3 TRS: 14N 2W | | | | | | | | 14N 2W 41 | | | | |
| DETAIL | | | | | | | | | | | | |
| Status: Cleanup Started NFA Received | | | No Is PSI | | | | | site? No | | | | |
| Statute: MTCA NFA Date: | | te: | N/A Curre | | | | | nt VCP? No Past VCP? No | | | | |
| Site Rank: N/A NFA Reason: | | | N/A | A Brownfie | | | | | eld? No | | | |
| Site Manager: Southwest Region Responsible | | | Southwest | west Active | | | | Institutional Control? No | | | | |
| CLEANUP UNITS | | | | | | | | | | | | |
| Cleanup Unit Name Unit Type | | Unit | Unit Status | | Unit Manager | | | Current Process | | | | |
| Centralia City Light Transformer Spill Upland | | Cleanup | Cleanup Started | | Southwest Regio | | on | Independent Action | | Action | | |
| ACTIVE INSTITUTIONAL CONTROLS | | | | | | | | | | | | |
| Instrument Type Restriction Media | Restrict | ictions/Requirements | | | Date Recor | | • | Recording County | | Tax Parcel | | |
| There are no current Institutional Controls in effect for this site. | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| AFFECTED MEDIA & CONTAMINANTS | | | | | | | | | | | | |
| | | | | | MEDIA | | | | | | | |
| Contaminant | | Soi | il Ground | water | Surface Water | | Sedim | ediment Air | | Bedrock | | |
| Petroleum-Other | | C | | | | | | | | | | |
| Key:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below | | | | | | | | | | | | |
| SITE ACTIVITIES | | | | | | | | | | | | |
| Activity | | | Status | | Start [| tart Date Co | | nd Date/ pletion Date | | | | |
| SHARP Assessment | | | | | Completed | | | | | | | |
| Site Discovery/Release Report Received | | | | C | Completed | | | | 12/27/2023 | | | |
| Initial Investigation / Federal Preliminary Assessment | | | | | Completed 5/13/202 | | | | /13/2024 | | | |