

Cleanup Site Details

Cleanup Site ID: 17152

Cleanup Site ID: 17152 Facility/Site ID: 24211 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Orchard Rite AST [Glossary](#)

Alternate Names: Orchard Rite AST, Orchard Rite AST Spill, Orchard Rite Union Gap

LOCATION

Address: 1615 W AHTANUM RD City: UNION GAP Zip Code: 98903 County: Yakima
Latitude: 46.55928 Longitude: -120.50080 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 12N 19E 6

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Orchard Rite AST	Upland	No Further Action Required	CE	Central Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		10/29/2024