

Cleanup Site Details

Cleanup Site ID: 17163

Cleanup Site ID: 17163 Facility/Site ID: 45971835 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Bradford Island Superfund [Glossary](#)

Alternate Names: Bonneville Dam, Bradford Island Superfund

LOCATION

Address: City: BONNEVILLE Zip Code: County: Skamania
Latitude: 45.64442 Longitude: -121.94077 WRIA: 28 Legislative District: 14 Congressional District: 3 TRS: 2N 7E 22

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: Federal - CERCLA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Chu, Valerie Responsible Unit: EPA Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Bradford Island Superfund Sediment	Sediment	Cleanup Started	EPA	Chu, Valerie	Federal-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Polychlorinated biPhenyls (PCB)				C		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/17/2022