

## Cleanup Site Details

Cleanup Site ID: 17191

Cleanup Site ID: 17191 Facility/Site ID: 8234187 UST ID: 7216 Site Page Site Documents View Map

Cleanup Site Name: Grant Cnty PUD Ephrata Service Center Glossary

Alternate Names: GPUD EPHRATA SERVICE CENTER, Grant Cnty PUD 2 Ephrata, Grant Cnty PUD Ephrata Service Center, Grant County PUD

Ephrata Service Center

LOCATION

Address: A ST & SE BLVD City: EPHRATA Zip Code: 98823 County: Grant

Latitude: 47.31670 Longitude: -119.55027 WRIA: 41 Legislative District: 13 Congressional District: 4 TRS: 21N 26E 15

**DETAIL** 

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 7/31/1997 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No

Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Grant County PUD Ephrata Service Center	Upland	No Further Action Required	EA	Eastern Region	Independent Action

## **ACTIVE INSTITUTIONAL CONTROLS**

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB					

Kev.

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date	
Site Discovery/Release Report Received	Completed		4/17/1997	
Initial Investigation / Federal Preliminary Assessment	Completed		6/26/1997	
Site Status Changed to NFA	Completed		7/31/1997	

Toxics Cleanup Program Report Generated: 8/23/2025 Page 1 of 1