

Cleanup Site Details

Cleanup Site ID: 17193

Cleanup Site ID: 17193 Facility/Site ID: 100003161 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Chelan Luxury Garages [Glossary](#)

Alternate Names: Chelan Luxury Garages, Chelan Luxury Garages LLC

LOCATION

Address: Corner of East Shop Ave and Jessie Street **City:** Chelan **Zip Code:** 98816 **County:** Chelan
Latitude: 47.83451 **Longitude:** -119.99545 **WRIA:** 47 **Legislative District:** 12 **Congressional District:** 8 **TRS:** 27N 23E 18

DETAIL

Status: Awaiting Cleanup **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** Yes **Past VCP?** Yes
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** No
Site Manager: Monahan, Mary **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chelan Luxury Garages	Upland	Awaiting Cleanup	CE	Monahan, Mary	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	C					
Lead	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		9/16/2024
VCP Opinion on Remedial Investigation	In Process	3/19/2025	