

Cleanup Site ID: 17205

Cleanup Site Details

Facility/Site ID: 82533369 UST ID: 507963 Site Page Site Documents View Map

Cleanup Site ID: 17205

Cleanup Site Name: Cameo Shop aka Cameo Boutique Glossary

Alternate Names: CAMEO SHOP, Cameo Shop aka Cameo Boutique

LOCATION

Address: 6871 E State Route 106 City: Union Zip Code: 98592 County: Mason

Latitude: 47.34777 Longitude: -123.07337 WRIA: 14 Legislative District: 35 Congressional District: 6 TRS: 22N 3W 33

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? Yes Past VCP? Yes

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Mullin, Tim Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Cameo Shop aka Cameo Boutique
 Upland
 Cleanup Started
 SW
 Mullin, Tim
 Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	В	В				
Other Non-Halogenated Organics	В	В				
Petroleum-Gasoline	RB	В				

Key:

B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/5/2025
VCP Receipt of Plan or Report	Completed		3/5/2025
VCP Opinion on Site Cleanup	Completed	3/5/2025	4/21/2025
Early Notice Letter(s)	Completed		3/19/2025
SHARP Assessment	Completed		3/19/2025
VCP Technical Assistance	Completed		4/8/2025

Toxics Cleanup Program Report Generated: 7/16/2025 Page 1 of 1