

## Cleanup Site Details

Cleanup Site ID: 17227

Cleanup Site ID: 17227 Facility/Site ID: 24956843 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Central Machinery Sales Inc E James St

Glossary

Alternate Names: CENTRAL MACHINERY SALES INC, Central Machinery Sales Inc E James St, Republic Services Canola Oil Based Biodiesel

Spill

LOCATION

Address: 1810 E James St City: Pasco Zip Code: 99301 County: Franklin

Latitude: 46.24809 Longitude: -119.07815 WRIA: 36 Legislative District: 16 Congressional District: 4 TRS: 9N 30E 20

**DETAIL** 

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 4/7/2025 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Initial Investigation Brownfield? No

Site Manager: Eastern Region Responsible Unit: Eastern Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Republic Service Canola Oil Based Biodiesel Spill	Upland	No Further Action Required	EA	Eastern Region	Independent Action

## **ACTIVE INSTITUTIONAL CONTROLS**

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	RB					

Kev.

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/22/2025
Initial Investigation / Federal Preliminary Assessment	Completed		4/3/2025
Site Hazard Assessment/Federal Site Inspection	Completed		4/3/2025
Site Status Changed to NFA	Completed		4/7/2025

Toxics Cleanup Program Report Generated: 5/7/2025 Page 1 of 1