

Cleanup Site Details

Cleanup Site ID: 1727

Cleanup Site ID: 1727	Facility/Site ID: 530	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Central Salvage					Glossary
Alternate Names: CENTRAL SALVAGE					

LOCATION

Address: 6 E RACE ST			City: YAKIMA	Zip Code: 98901	County: Yakima
Latitude: 46.59314	Longitude: -120.50289	WRIA: 37	Legislative District: 14	Congressional District: 4	TRS: 13N 19E 19

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 12/28/1995	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Site Hazard Assessment	Brownfield? No
Site Manager: Bassett, Dick	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Central Salvage	Upland	No Further Action Required	CE	Bassett, Dick	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Corrosive Wastes	S					
Petroleum Products-Unspecified	S					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/17/1992
Initial Investigation / Federal Preliminary Assessment	Completed		11/18/1992
Site Hazard Assessment	Completed	2/10/1995	6/29/1995
Site Status Changed to NFA	Completed		12/28/1995