

Cleanup Site Details

Cleanup Site ID: 1727

Cleanup Site ID: 1727 Facility/Site ID: 530 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Central Salvage Glossary

Alternate Names: CENTRAL SALVAGE

LOCATION

Address: 6 E RACE ST City: YAKIMA Zip Code: 98901 County: Yakima

Latitude: 46.59314 Longitude: -120.50289 WRIA: 37 Legislative District: 14 Congressional District: 4 TRS: 13N 19E 19

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 12/28/1995 Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: Site Hazard Assessment Brownfield? No

Site Manager: Bassett, Dick Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name Unit Type Unit Status Resp Unit Unit Manager Current Process

Central Salvage Upland No Further Action Required CE Bassett, Dick Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Corrosive Wastes	S					
Petroleum Products-Unspecified	S					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		8/17/1992
Initial Investigation / Federal Preliminary Assessment	Completed		11/18/1992
Site Hazard Assessment	Completed	2/10/1995	6/29/1995
Site Status Changed to NFA	Completed		12/28/1995

Toxics Cleanup Program Report Generated: 10/22/2025 Page 1 of 1