

Cleanup Site Details

Cleanup Site ID: 17295

Cleanup Site ID: 17295 Facility/Site ID: 100004503 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: US-12 MP 138 USDOT ROW [Glossary](#)

Alternate Names: US 12 MP 138 USDOT ROW, US-12 MP 138 USDOT ROW

LOCATION

Address: US 12 MP 138 ROW City: Randle Zip Code: 98377 County: Lewis
Latitude: 46.68844 Longitude: -121.57996 WRIA: 26 Legislative District: 20 Congressional District: 3 TRS: 14N 10E 20

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Southwest Region Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
US-12 MP138 WSDOT ROW	Upland	Awaiting Cleanup	SW	Southwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	S	S				
Other Non-Halogenated Organics	S	S				
Petroleum-Diesel	S	S				
Petroleum-Other	S	S				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		4/3/2024
Initial Investigation / Federal Preliminary Assessment	Completed		7/14/2025
SHARP Assessment	Completed		7/29/2025
Early Notice Letter(s)	Completed		8/20/2025